для размещения заказа - kennametal@kennametal.su

STELLRAM

5400VM Technical Information





Stellram recommends the use of method a) whenever possible.
Compressed air or sufficient coolant is used to ensure adequate chip evacuation.

Note: Machining method a) is preferred as this method greatly reduces vibration.

для заказа - kennametal@kennametal.su