




Torque values for mounting bolts

Excessive condition is when long reach extensions are required or when cutting parameters are elevated to extreme parameters.

5230VS09	Detail 1			Detail 2	
Cutter	Mounting Bolt Description	**Torque Values in Nm for Mounting Bolt		Coolant Plug Description	Coolant Plug tightening Nm
		Normal Condition	Excessive Condition		
5230VS09-A050Z4R51	M12-1.75 ISO x 30mm SHCS	80	100	SB-3413	34
5230VS09-A050Z4R80				SB-3621	

5230VS12	Detail 1			Detail 2	
Cutter	Mounting Bolt Description	**Torque Values in Nm for Mounting Bolt		Coolant Plug Description	Coolant Plug tightening Nm
		Normal Condition	Excessive Condition		
5230VS12-A063Z4R57	M12-1.75 ISO x 30mm SHCS	80	100	SB-3229	34
5230VS12-A063Z4R94				SB-3230	
5230VS12-A080Z5R65	M16-2 ISO x 40mm SHCS	110	150	SB-3231	61
5230VS12-A080Z5R110				SB-3232	
5230VS12-A100Z6R76	M20-2.5 ISO x 50mm SHCS	120	180	SB-3233	61
5230VS12-A100Z6R133				SB-3234	

Hex Keys

M12 = Hex Key Size 10
M16 = Hex Key Size 14
M20 = Hex Key Size 17